Bldg
357

DOCK
33
033
REMOVE BEFORE FLIGHT
AFMC

WELCOME TO F-16
FALCON COUNTRY

LIFT





Solder slag caused this aircraft component to short out.

Because this valve was not properly capped a bug was able to make a cocoon in the valve causing this aircraft component to fail.